

Bin Store Unsuitable Examples – April 2025

The bins shown represent unsuitable in terms of waste. You are advised to approach the Local Planning Authority for further guidance.



This bin store is not suitable due to the low lintel and chain attached to bin. This will prevent collection.



This bin store is not suitable due to the low lintel, chain attached to bin, and needing to use a wedge to hold up the roof. This will prevent collection.



This bin store is not suitable due to the low lintel and chain attached to bin, which will prevent collection.